W-02211A-14-049





ORIGINAL

Investigator.	Phone:	Fax:	
Priority: Respond Within Five Days			

Last:

<u>Opinion</u> <u>No.</u> 2015 - 120435 <u>Date:</u> 1/12/2015

<u>Complaint Description:</u> 08A Rate Case Items - Opposed

N/A Not Applicable First:

Complaint By: Susan Breshears

Account Name: Susan Breshears Home:

Street: Work:

City: Clifton CBR:

<u>State:</u> AZ <u>Zip:</u> 85533 <u>is:</u>

Utility Company. Loma Linda Estates, Inc. d/b/a Loma Linda Water Company

**Division:** Water

**AZ Corporation Commission** 

Contact Name: Contact Phone:

Nature of Complaint:

DOCKET NO. W-02211A-14-0419 OPPOSED TO INCREASE

Arizona Corporation Commission

DOCKETED

1200 West Washington Street
Phoenix, AZ 85007 FEB 1 7 2015

Phoenix, AZ 85007 FED 1 7 2
Utilities Division

To Whom it May Concern:

Receiving the notification from Loma Linda Water Co. is not a surprise, but saying they need finacing to repair or replace the infrastructure is simply wanting more money in their pockets. There has been (1) one repair made to something concerning computer parts to the pumps seems like last Spring we had virtually a trickle of water for 3 or 4 days! It was stated they were looking for someone who could the work! The wed. Thur., & Friday before the work was actually done on the weekend, it was not made known what the problem was. It was made known to customers by phone the last minute, I was told that they didn't call me because they didn't have my phone number- which is a lie-! I been here almost 37 years. As any other repairs in that 37 years, there have been lines rerouted, but breaks in water lines have not been repaired! Not knowing exactly how the lines cross the streets, it could be one or more broken and leaking for all these 37 years.

At the entrance to Loma Linda, in the winter time there is water, wet areas in the road. The payment at times, stands small puddles, which don't show in the summer. Which the hot tempatures evaporates. I'm sure I'm not the only one who sees the water, these have never in the 37 years been repaired. They are not rain puddles, they are still in the road long after the tempature goes back up to typical warm winter tempatures.

Where is all the financial means they have received for 37 years to do repairs they've never done!?!

## ARIZONA CORPORATION COMMISSION UTILITY COMPLAINT FORM

Thank you

Susan M. Breshears

Morenci, Az 85540

Residence: Clifton, AZ 85533

C.C. Enclosed copy of the letter concerning reading meters Early & Late! \*End of Complaint\*

## **Utilities' Response:**

## **Investigator's Comments and Disposition:**

SEE COMPLAINT 110572 FOR LETTER REFERENCED IN THIS OPINION. \*End of Comments\*

Date Completed: 1/12/2015

Opinion No. 2015 - 120435